



# TOUCH PROBE

---

## INFORMATIONS OF PROBE (TOUCH PROBE)

2016. 12. 30

KIHEUNG MACHINERY Co.,Ltd



# TOUCH PROBE

## Probe calibration

### 1. What calibration is :

Generally spindle has some tolerance and stylus also has its tolerance when it is clamping in spindle and it needs to be adjusted the tolerance lower by calibration cycle.

### 2. How to command

G65 P9019 D\_ S\_



Ex) G65 P9019 D29.999 S54.

Here variables :

D = Ring gauge diameter

S = Center setting coordinates of ring gauge

(S54 ~ S59 => G54 ~ G59)






# TOUCH PROBE

## Measuring result

### 1. Measured result is memorized into macro variables :

- #900 = X axis direction stylus ball radius(X RAD)
- #901 = Y axis direction stylus ball radius(XY RAD)
- #902 = X axis eccentricity
- #903 = Y axis eccentricity



### 2. How to compensate

- 1) Measure center of ring and enter machine position(X, Y) into work coordinates that you want



- 2) Installing touch probe

Here variables :

D = Ring gauge diameter

S = Center setting coordinates of ring gauge


(S54 ~ S59 => G54 ~ G59)



- 3) Moving probe to the center of ring by Handle or Jog

- 4) Changing MDI MODE and running :

G65 P9019 D29.999 S54 ;





# TOUCH PROBE

## X, Y, Z Single Surface Measurement

### 1. What is :

To decide the measured surface as basement, refresh work offset.  
And after measuring return to the start point..

### 2. Commanding :

```
G65 P9019 A1 X_ Y_ Z_ S_ [I, J, K]
```

Ex)


```
G65 P9019 A1. X10. S54
```

Parameters : necessary

A1        Single surface measurement(Necessary)  
X, Y, Z    Distance from measuring surface (X or Y or Z)  
S        Work offset (S54 ~ S59 => G54 ~G59)

Parameters : optional

I, J, K    Distance from workpiece coordinates





# TOUCH PROBE


## 3. Method :

- 1) Changing tool to probe.
- 2) Moving probe adjacent to the measuring surface 1  
(About 10mm ~ 15mm)

- 3) In MDI MODE executing :

G65 P9019 A1. X-10. I50. S54

- 4) Into X axis coordinate of G54 entering +50 automatically  
(Also measuring Y and Z axis as same)



Ex)

O1000 (Z)


G65 P9019 A1. Z-20. S59 K0.

O1001 (X)

G65 P9019 A1. X-20. S59 I0.

O1002 (Y)

G65 P9019 A1. Y-20. S59 J0.





# TOUCH PROBE

## Boss(Hole outer surface) Measurement

### 1. What is :

To set up work offset to center of hole or measure hole outer diameter offset.  
And after measuring return to the start point..

### 2. Commanding :

G65 P9019 A2 D\_ Z\_ S\_



Ex)

G65 P9019 A2. D20. Z15. S54

Parameters : necessary

A2	Boss measurement(Necessary)
D	Hole outer diameter
Z	Measuring position from stylus (Absolute)
S	Work offset (S54 ~ S59 => G54 ~G59)

#916      Hole outer diameter






# TOUCH PROBE

## 3. Method :


- 1) Changing tool to probe.
- 2) Moving probe adjacent to the measuring surface 1  
(About 10mm ~ 15mm)
- 3) In MDI MODE executing :  
G65 P9019 A2. D20. Z15. S54
- 4) Into X, Y axis coordinates of G54 entering current X, Y values automatically



Ex)

O3000 (HOLE)

G65 P9019 A2. D30. S59. Z-20.





# TOUCH PROBE

## Bore(Hole inner surface) Measurement

### 1. What is :

To set up work offset to center of hole or measure hole inner diameter offset.

### 2. Commanding :

G65 P9019 A2 D\_ S\_



Ex)

G65 P9019 A2. D20. S54

Parameters : necessary

A2	Bore measurement(Necessary)
D	Hole inner diameter
S	Work offset (S54 ~ S59 => G54 ~G59)

#916      Hole inner diameter








# TOUCH PROBE

## 3. Method :


- 1) Changing tool to probe.
- 2) Moving probe adjacent to the measuring surface 1 (near center)
- 3) In MDI MODE executing :  
G65 P9019 A2. D20. S54
- 4) Into X, Y axis coordinates of G54 entering current X, Y values automatically



Ex)

O3000 (HOLE)

G65 P9019 A2. D30. S59.





# TOUCH PROBE

## Web(Outer surface) Measurement

### 1. What is :

To set up work offset to center of rectangular or measure X, Y outer width.

### 2. Commanding :

G65 P9019 A3 X\_ Y\_ Z\_ S\_ [I\_ J\_]

Ex)



G65 P9019 A3. X20. Y30. Z-15. S54.

Parameters : necessary

A3	Web measurement(Necessary)
X, Y	Each width
Z	Measuring position from stylus (Absolute)
S	Work offset (S54 ~ S59 => G54 ~G59)

Parameters : optional

I, J	Distance from workpiece coordinates
#917	Web outer width






# TOUCH PROBE

## 3. Method :

- 1) Changing tool to probe.
- 2) Moving probe adjacent to the measuring surface 1  
(About 10mm ~ 15mm)
- 3) In MDI MODE executing :  
G65 P9019 A3. X30.. Z-15. S54
- 4) Into X, Y axis coordinates of G54 entering current X, Y values automatically




Ex)

O2000 (X)

G65 P9019 A3. X30. S59. Z-20.

O2001 (Y)

G65 P9019 A3. Y20. S59. Z-20.





# TOUCH PROBE

## Pocket(Inner surface) Measurement

### 1. What is :

To set up work offset to center of rectangular or measure X, Y inner width.

### 2. Commanding :

G65 P9019 A3 X\_ Y\_ S\_ [I\_ J\_]

Ex)



G65 P9019 A3. X20. Y30. S54.

Parameters : necessary

A3	Web measurement(Necessary)
X, Y	Each width
S	Work offset (S54 ~ S59 => G54 ~G59)

Parameters : optional

I, J	Distance from workpiece coordinates
#917	Web inner width






# TOUCH PROBE

## 3. Method :

- 1) Changing tool to probe.
- 2) Moving probe adjacent to the measuring surface 1 (near center)
- 3) In MDI MODE executing :  
G65 P9019 A3. X20.. S54
- 4) Into X, Y axis coordinates of G54 entering current X, Y values automatically




Ex)

O2000 (X)

G65 P9019 A3. X20. S59.

O2001 (Y)

G65 P9019 A3. Y20. S59.





# TOUCH PROBE

## Corner Measurement

### 1. What is :

To set up work offset to corner X, Y, Z of rectangular altogether.

### 2. Commanding :

G65 P9019 A4 C\_ X\_ Y\_ S\_ [I\_ J\_]

Ex)


G65 P9019 A4. C1. S54.

Parameters : necessary

- A4 Corner measurement(Necessary)
- C Position of measuring corner
- X, Y, Z Measuring distance from corner (about 15mm)
- S Work offset (S54 ~ S59 => G54 ~G59)

Parameters : optional

- I, J, K Distance from workpiece coordinates
- #916 Designation of measuring distance from corner





# TOUCH PROBE

## 3. Method :



1) Changing tool to probe.

2) Moving probe adjacent to the measuring surface C1  
(About 10mm ~ 15mm above Z axis surface)

3) In MDI MODE executing :

G65 P9019 A4. C1. S54

4) Into X, Y and Z axis coordinates of G54 entering current X, Y and Z values automatically





# TOUCH PROBE

## Angle Measurement

### 1. What is :

To get angle between two points of one surface.

### 2. Commanding :

G65 P9019 A5 X\_ Y\_ I\_ J\_

Ex)



G65 P9019 A5. X10. J30.

Parameters : necessary

- A5      Angle measurement(Necessary)
- X, Y    Measuring distance from measuring surface (X or Y)
- I, J      Incremental distance between first measuring point to second

Result

#914      Measured angle








# TOUCH PROBE

## 3. Method :

- 1) Changing tool to probe.
- 2) Moving probe adjacent to the measuring position P1  
(About 10mm ~ 15mm)
- 3) In MDI MODE executing :  
G65 P9019 A5. A5. Y10. I30.
- 4) Output results into #914 after measuring two points of one surface



Ex)

O4000(ANGLE SHIFT)  
G65 P9019 A5. Y20. I30.

